Parts & Service Information

Subject: Starting Problems Because of

Sticking Fuel Pump Check Valve

Application: Certain 1990 900 and 9000 Models

CATEGORY	-
Engine	
SECTION	PAGE
2	7
ISSUE	CODE
11 (00, 005)	234

The fuel pump check valve for the new "positive feed" ejector fuel pump is located in the fuel line elbow that fits into the top of the pump (see PSI On some cars equipped with the positive feed pump, the check valve may stick, resulting in longer engine cranking on restart because of the loss of fuel system rest pressure.

Cars affected:

Check Valve Replacement Procedure


Verifythat the check valve is faulty by checking the fuel system rest pressure. If the check valve is sticking, the rest pressure will rapidly drop to zero after the engine off is shut off.

- 1. Remove the trunk floor to gain access to the top of the fuel pump.
- 2. Remove the fuel supply fitting/check valve from the pump.

WARNING

Always observe the talked safety when working on the fuel system

- ı N o
- A Fire Extinguisher Nearby.
- Wear Eye Protection.
- Work in A Well Ventilated Area (Use Vapor Extraction Equipment if Available.)
- Avoid Prolonged SkIn Contact With Fuel And Wear Suitable Gloves.



- 3) III.
- 4) Return

Remove the check valve by cutting the plastic fuel line 12-14 mm from the end of the line as shown in Figure 2.

Note

The fuel line must not be trimmed more than If more than is removed, the line be too short and will have to be replaced.

- **4.** Fit special tool P/N 83 94 546 onto the fuel line as shown in Figure 3.
- 5. Press the new check valve, P/N 41 61766, into the fuel line (Figure 3).
- 6. Install two new O-rings (P/N 79 74 546) on the check valve.

Note

New O-rings must be used each time the check valve fitting is installed. These O-rings swell when exposed to fuel vapor and therefore cannot be reused.

- **7.** Reinstall the check valve into the top of the pump.
- Start the engine and check that there are no fuel leaks.
- 9. Reinstall the trunk floor.

Warranty Information:

For Warranty Claims, use Failure Coding 24115-23-0-01-01. Time allowance is 0.6 hour straight time for 9000 and 0.4 hour straight for the 900.



Figure 2. Cut off the old check valve, 12-14 mmfrom the end.



- 3. Title a check valve
 - 1) tool P/N 83 94 546
 - 2) Check valve P/N 41 61 766 3) O-rings P/N 79 74 546